


STCA*****W3 Series Soldering Operation Instruction

一、Product Appearance Identification Drawing:



二、Effective drawing shows as below after completion of part soldering, soldering will be done with the contact of bottom side and microstrip line, silkprint mark must be upwards in order to identify the part number and specification. It may have influence on the part reliability if not use part with correct soldering in comply with operation instruction.

