


# WTCA\*\*\*\*\*SMT Series Soldering Operation Instruction

## 一、Product Appearance Identification Drawing:



二、Effective drawing shows as below after completion of part soldering,soldering will be done with the contact of bottom side and microstrp line, black isolating resin must be upwards. It may have influence on the part reliability if not use part with correct soldering in comply with operation instruction.

